IMPORTANT SAFETY NOTICE

May 2015

Re: Recall to Inspect and Repair

Certain 2011 - 2014 TenPoint and Wicked Ridge Crossbows:

Consumer Test Procedure

Dear TenPoint Customer:

Product safety is our top priority.

In cooperation with the U.S. Consumer Product Safety Commission, TenPoint Crossbow Technologies is announcing a voluntary recall to repair certain TenPoint and Wicked Ridge crossbows. TenPoint is requesting that owners of these models conduct a self-inspection to determine if their crossbow requires the recall and repair.

TenPoint has discovered that arrows can release from certain crossbows following a sequence of actions involving: 1. pulling the trigger when the safety is on "safe", 2. moving the safety slide to "fire", 3. attempting unsuccessfully to return the safety to "safe", and 4. pulling the trigger a second time believing the trigger is on "safe".

How do I know if my crossbow is affected?

The voluntary recall to inspect - and repair if necessary - applies to certain TenPoint and Wicked Ridge crossbows manufactured from 2011 to 2014. A complete list of the crossbow models and serial numbers is displayed in the chart following this letter. The serial number is located on the left side of the crossbow barrel below the trigger box.

If your crossbow is listed below, please follow the attached self-test procedure to determine whether it requires a repair and, if so, how to return it to TenPoint free of charge. If you are not familiar with the safe-use rules contained in your Owner's Manual, or if you do not feel comfortable conducting the test, call TenPoint at the number below.

For more information, including a self-test video, please visit http://www.wickedridgecrossbows.com and click on "Recall to Repair – Self Test". You may also contact TenPoint by email at safetyrecall@tenpointcrossbows.com or by phone at (800) 548-6837 (from 9:00 a.m. to 5:00 p.m. ET Monday through Friday).

Thank you for your cooperation.

Sincerely,

Hunter's Manufacturing Company Inc.

Model	Serial Number Range
TenPoint Shadow Ultra-Lite:	G000001-G006449
• Model numbers C14018-7521 and C14018-7522	
TenPoint Turbo XLT II:	F54796-F55233
 Model Numbers C12020-4920, C12020-4521, and C12020-4522 	G50000-G55924
	H50000-H54851
	F000001-F007055
TenPoint Titan Extreme:	F88113-F91878
• Model Numbers C12047-6520, C12047-6521, C12047-6522, C13047-1912, and C13047-5312	G80001-G89999
	H80000-H96243
	H000001-H015400
TenPoint Maverick HP:	F41618-F41909
• Model Numbers C11055-3000, C11055-3521,	G40000-G40353
C11055-3522, C11055-6000, C11055-6520, C11055-6521, and C11055-6522	
TenPoint GT Flex:	F70173-F70299
 Model Numbers C08066-3000, C08066-3420, C08066-3421, C08066-3422, C08066-3430, C08066-3431, C08066-3432, C14066-1000, C14066-1330, C14066-1331, and C14066-1332 	G70000-G70151
	H70000-H70299
	I000001-I000452
TenPoint Phantom CLS-S:	F00002-F00261
• Model numbers C10003-4211, C10003-4212,	G00001-G00156
C10003-4221, and C10003-4222	
Wicked Ridge Raider CLS:	V70000-V72011
 Model numbers WR1221.6230, WR1221.6336, and WR1221.6326 	W70001-W71806
	J000001–J000831
Wicked Ridge Invader HP:	V00000-V20881
 Model numbers WR1205.6446, WR1205.6336, and WR1205.6436 	W01437-W10261
	K000001-K008644
Wicked Ridge Warrior HL:	W40000-W55874
 Model numbers WR1215.6440, WR1215.6330, WR1215.6430, and WR1415.1436 	V40000-V52357
	L000001-L011095